



## Lundgren/BJFE set

Easy, only four solderings; Solder blue from five way switch to ground  
Solder yellow from five way switch to ground  
The direction of the components does not matter.

